


Peacock- Δ 10

Lab 5b-Color Wheel 2


Peacock

Original
062922-1

Neph Sy	36.62
Barium Carb	46.57
EPK	6.63
Flint	10.19
Copper Carbonate	3.09
Water	60



1-3 Second Dip



2-3 Second Dips

Oxidation




Reduction



UMF

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.25		Alkaline Earths 0.75	
SiO ₂ 1.88	Collective "Al ₂ O ₃ " 0.32	Na ₂ O 0.19	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.32	Li ₂ O	CuO	SrO	BaO 0.74
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



EUMF

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.30		Alkaline Earths 0.70	
SiO ₂ 1.74	Collective "Al ₂ O ₃ " 0.30	Na ₂ O 0.18	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.30	Li ₂ O	CuO 0.07	SrO	BaO 0.69
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO




Ceramic
Materials
Workshop

Peacock

Neph Sy	35.90
Barium Carb	45.65
EPK	6.50
Flint	9.99
Cobalt Carbonate	0.98
Chrome Oxide	0.98
Water	60




1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.24		Alkaline Earths 0.76	
SiO ₂ 1.83	Collective "Al ₂ O ₃ " 0.32	Na ₂ O 0.19	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.31	Li ₂ O	CuO	SrO	BaO 0.72
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃ 0.02	ZrO ₂	P ₂ O ₅		MnO ₂	CoO 0.03




Ceramic
Materials
Workshop


ceramicmaterialsworkshop.com

Peacock

Neph Sy	35.21
Barium Carb	44.77
EPK	6.37
Flint	9.80
Cobalt Carbonate	0.96
Copper Carbonate	2.88
Water	60



1-3 Second Dip




2-3 Second Dips



Reduction

Oxidation

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.29		Alkaline Earths 0.71	
SiO ₂ 1.71	Collective "Al ₂ O ₃ " 0.29	Na ₂ O 0.17	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.29	Li ₂ O	CuO 0.07	SrO	BaO 0.67
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO 0.02




Ceramic
Materials
Workshop

Peacock

Neph Sy	34.22
Barium Carb	43.52
EPK	6.20
Flint	9.52
Cobalt Carbonate	0.93
Red Iron Oxide	5.61
Water	60




1-3 Second Dip



2-3 Second Dips




Reduction



Oxidation

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.17		Alkaline Earths 0.83	
SiO ₂ 1.34	Collective "Al ₂ O ₃ " 0.23	Na ₂ O 0.14	K ₂ O 0.04	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.23	Li ₂ O	CuO	SrO	BaO 0.53
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.27
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO 0.02




Ceramic
Materials
Workshop

Peacock

Neph Sy	35.21
Barium Carb	44.77
EPK	6.37
Flint	9.80
Cobalt Carbonate	0.96
Manganese Dioxide	2.88
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.22		Alkaline Earths 0.78	
SiO ₂ 1.66	Collective "Al ₂ O ₃ " 0.29	Na ₂ O 0.17	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.28	Li ₂ O	CuO	SrO	BaO 0.65
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂ 0.10	CoO 0.02



Ceramic
Materials
Workshop

ceramicmaterialsworkshop.com

Peacock

Neph Sy	35.38
Barium Carb	44.99
EPK	6.40
Flint	9.84
Cobalt Carbonate	0.97
Nickel Carb (Green)	2.42
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 4.82 :1		Alkali Metals 0.24		Alkaline Earths 0.76	
SiO ₂ 1.83	Collective "Al ₂ O ₃ " 0.38	Na ₂ O 0.19	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.31	Li ₂ O	CuO	SrO	BaO 0.72
TiO ₂ 0.00	NiO 0.06	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO 0.03




Ceramic
Materials
Workshop


ceramicmaterialsworkshop.com

Peacock


Neph Sy	34.22
Barium Carb	43.52
EPK	6.20
Flint	9.52
Cobalt Carbonate	0.93
Titanium Dioxide	5.61
Water	60




1-3 Second Dip



2-3 Second Dips




Reduction



Oxidation

SiO ₂ :Al ₂ O ₃ Ratio 3.38 :1		Alkali Metals 0.24		Alkaline Earths 0.76	
SiO ₂ 1.83	Collective "Al ₂ O ₃ " 0.54	Na ₂ O 0.19	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.31	Li ₂ O	CuO	SrO	BaO 0.72
TiO ₂ 0.23	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO 0.03



Ceramic
Materials
Workshop

Peacock

Neph Sy	34.55
Barium Carb	43.93
EPK	6.25
Flint	9.61
Cobalt Carbonate	0.94
Tin Oxide	4.72
Water	60




1-3 Second Dip



2-3 Second Dips




Reduction



Oxidation

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.31		Alkaline Earths 0.69	
SiO ₂ 1.66	Collective "Al ₂ O ₃ " 0.29	Na ₂ O 0.17	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.29	Li ₂ O	CuO	SrO	BaO 0.66
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂ 0.09	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO 0.02




Ceramic
Materials
Workshop

Peacock


Neph Sy	32.99
Barium Carb	41.95
EPK	5.97
Flint	9.18
Cobalt Carbonate	0.90
Ultrax (Zircopax)	9.01
Water	60



1-3 Second Dip




2-3 Second Dips



Reduction

Oxidation

SiO ₂ :Al ₂ O ₃ Ratio 6.33 :1		Alkali Metals 0.24		Alkaline Earths 0.76	
SiO ₂	Collective "Al ₂ O ₃ "	Na ₂ O	K ₂ O	MgO	CaO
2.00	0.32	0.19	0.05	0.00	0.01
B ₂ O ₃	Al ₂ O ₃	Li ₂ O	CuO	SrO	BaO
	0.31				0.72
TiO ₂	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO
0.00					0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO
					0.03



Ceramic
Materials
Workshop

Peacock

Neph Sy	35.21
Barium Carb	44.77
EPK	6.37
Flint	9.80
Chrome Oxide	0.96
Copper Carbonate	2.86
Water	60



1-3 Second Dip



2-3 Second Dips


Oxidation



Reduction



SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.30		Alkaline Earths 0.70	
SiO ₂ 1.75	Collective "Al ₂ O ₃ " 0.30	Na ₂ O 0.18	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.30	Li ₂ O	CuO 0.07	SrO	BaO 0.69
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃ 0.02	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop

ceramicmaterialsworkshop.com

Peacock

Neph Sy	34.22
Barium Carb	43.52
EPK	6.20
Flint	9.52
Chrome Oxide	0.93
Red Iron Oxide	5.61
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.18		Alkaline Earths 0.82	
SiO ₂ 1.37	Collective "Al ₂ O ₃ " 0.24	Na ₂ O 0.14	K ₂ O 0.04	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.23	Li ₂ O	CuO	SrO	BaO 0.54
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.28
Cr ₂ O ₃ 0.02	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop


ceramicmaterialsworkshop.com

Peacock

Neph Sy	35.21
Barium Carb	44.77
EPK	6.37
Flint	9.80
Chrome Oxide	0.96
Manganese Dioxide	2.88
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.22		Alkaline Earths 0.78	
SiO ₂ 1.70	Collective "Al ₂ O ₃ " 0.29	Na ₂ O 0.17	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.29	Li ₂ O	CuO	SrO	BaO 0.67
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃ 0.02	ZrO ₂	P ₂ O ₅		MnO ₂ 0.10	CoO



Ceramic
Materials
Workshop

ceramicmaterialsworkshop.com

Peacock

Neph Sy	35.38
Barium Carb	44.99
EPK	6.40
Flint	9.84
Chrome Oxide	0.97
Nickel Carb (Green)	2.42
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 4.82 :1		Alkali Metals 0.25		Alkaline Earths 0.75	
SiO ₂ 1.88	Collective "Al ₂ O ₃ " 0.39	Na ₂ O 0.19	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.32	Li ₂ O	CuO	SrO	BaO 0.74
TiO ₂ 0.00	NiO 0.07	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃ 0.02	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop

ceramicmaterialsworkshop.com

Peacock

Neph Sy	34.22
Barium Carb	43.52
EPK	6.20
Flint	9.52
Chrome Oxide	0.93
Titanium Oxide	5.61
Water	60



1-3 Second Dip



2-3 Second Dips




Reduction



Oxidation

SiO ₂ :Al ₂ O ₃ Ratio 3.38 :1		Alkali Metals 0.25		Alkaline Earths 0.75	
SiO ₂ 1.88	Collective "Al ₂ O ₃ " 0.56	Na ₂ O 0.19	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.32	Li ₂ O	CuO	SrO	BaO 0.74
TiO ₂ 0.23	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃ 0.02	ZrO ₂	P ₂ O ₅		MnO ₂	CoO




Peacock

Neph Sy	34.55
Barium Carb	43.93
EPK	6.25
Flint	9.61
Chrome Oxide	0.94
Tin Oxide	4.72
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.32		Alkaline Earths 0.68	
SiO ₂ 1.70	Collective "Al ₂ O ₃ " 0.29	Na ₂ O 0.17	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.29	Li ₂ O	CuO	SrO	BaO 0.67
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂ 0.09	ZnO	FeO 0.00
Cr ₂ O ₃ 0.02	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop

ceramicmaterialsworkshop.com

Peacock

Neph Sy	32.99
Barium Carb	41.95
EPK	5.97
Flint	9.18
Chrome Oxide	0.90
Ultrox (Zircopax)	9.01
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 6.33 :1		Alkali Metals 0.25		Alkaline Earths 0.75	
SiO ₂ 2.05	Collective "Al ₂ O ₃ " 0.32	Na ₂ O 0.19	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.32	Li ₂ O	CuO	SrO	BaO 0.74
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃ 0.02	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop

Peacock

Neph Sy	33.59
Barium Carb	42.72
EPK	6.08
Flint	9.35
Copper Carbonate	2.75
Red Iron Oxide	5.50
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.22		Alkaline Earths 0.78	
SiO ₂ 1.29	Collective "Al ₂ O ₃ " 0.22	Na ₂ O 0.13	K ₂ O 0.04	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.22	Li ₂ O	CuO 0.05	SrO	BaO 0.51
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.26
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop

ceramicmaterialsworkshop.com

Peacock

Neph Sy	34.55
Barium Carb	43.93
EPK	6.25
Flint	9.61
Copper Carbonate	2.83
Manganese Dioxide	2.83
Water	60



1-3 Second Dip



2-3 Second Dips




Reduction



Oxidation

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.27		Alkaline Earths 0.73	
SiO ₂ 1.59	Collective "Al ₂ O ₃ " 0.27	Na ₂ O 0.16	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.27	Li ₂ O	CuO 0.06	SrO	BaO 0.63
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂ 0.09	CoO



Ceramic
Materials
Workshop

Peacock

Neph Sy	34.71
Barium Carb	44.14
EPK	6.28
Flint	9.66
Copper Carbonate	2.84
Nickel Carb (Green)	2.37
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 4.82 :1		Alkali Metals 0.30		Alkaline Earths 0.70	
SiO ₂ 1.75	Collective "Al ₂ O ₃ " 0.36	Na ₂ O 0.18	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.30	Li ₂ O	CuO 0.07	SrO	BaO 0.69
TiO ₂ 0.00	NiO 0.06	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop


ceramicmaterialsworkshop.com

Peacock

Neph Sy	33.59
Barium Carb	42.72
EPK	6.08
Flint	9.35
Copper Carbonate	2.75
Titanium Dioxide	5.50
Water	60



1-3 Second Dip




2-3 Second Dips



Oxidation

Reduction

SiO ₂ :Al ₂ O ₃ Ratio 3.38 :1		Alkali Metals 0.30		Alkaline Earths 0.70	
SiO ₂ 1.75	Collective "Al ₂ O ₃ " 0.52	Na ₂ O 0.18	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.30	Li ₂ O	CuO 0.07	SrO	BaO 0.69
TiO ₂ 0.22	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO




Ceramic
Materials
Workshop

Peacock

Neph Sy	33.91
Barium Carb	43.12
EPK	6.14
Flint	9.43
Copper Carbonate	2.78
Tin Oxide	4.63
Water	60




1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.36		Alkaline Earths 0.64	
SiO ₂ 1.59	Collective "Al ₂ O ₃ " 0.27	Na ₂ O 0.16	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.27	Li ₂ O	CuO 0.06	SrO	BaO 0.63
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂ 0.09	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop

ceramicmaterialsworkshop.com

Peacock

Neph Sy	32.41
Barium Carb	41.21
EPK	5.87
Flint	9.02
Copper Carbonate	2.65
Ultrax (Zircopax)	8.85
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 6.33 :1		Alkali Metals 0.30		Alkaline Earths 0.70	
SiO ₂ 1.91	Collective "Al ₂ O ₃ " 0.30	Na ₂ O 0.18	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.30	Li ₂ O	CuO 0.07	SrO	BaO 0.69
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop

ceramicmaterialsworkshop.com

Peacock

Neph Sy	33.59
Barium Carb	42.72
EPK	6.08
Flint	9.35
Red Iron Oxide	5.50
Manganese Dioxide	2.75
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.17		Alkaline Earths 0.83	
SiO ₂ 1.27	Collective "Al ₂ O ₃ " 0.22	Na ₂ O 0.13	K ₂ O 0.04	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.22	Li ₂ O	CuO	SrO	BaO 0.50
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.26
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂ 0.07	CoO



Ceramic
Materials
Workshop

Peacock

Neph Sy	33.75
Barium Carb	42.92
EPK	6.11
Flint	9.39
Red Iron Oxide	5.53
Nickel Carb (Green)	2.30
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 4.82 :1		Alkali Metals 0.18		Alkaline Earths 0.82	
SiO ₂ 1.37	Collective "Al ₂ O ₃ " 0.28	Na ₂ O 0.14	K ₂ O 0.04	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.23	Li ₂ O	CuO	SrO	BaO 0.54
TiO ₂ 0.00	NiO 0.05	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.28
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO




Ceramic
Materials
Workshop


ceramicmaterialsworkshop.com

Peacock

Neph Sy	32.69
Barium Carb	41.58
EPK	5.92
Flint	9.10
Red Iron Oxide	5.36
Titanium Dioxide	5.36
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 3.38 :1		Alkali Metals 0.18		Alkaline Earths 0.82	
SiO ₂ 1.37	Collective "Al ₂ O ₃ " 0.40	Na ₂ O 0.14	K ₂ O 0.04	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.23	Li ₂ O	CuO	SrO	BaO 0.54
TiO ₂ 0.17	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.28
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop

Peacock


Neph Sy	32.99
Barium Carb	41.95
EPK	5.97
Flint	9.18
Red Iron Oxide	5.41
Tin Oxide	4.50
Water	60



1-3 Second Dip




2-3 Second Dips



Reduction

Oxidation

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.24		Alkaline Earths 0.76	
SiO ₂ 1.27	Collective "Al ₂ O ₃ " 0.22	Na ₂ O 0.13	K ₂ O 0.04	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.22	Li ₂ O	CuO	SrO	BaO 0.50
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂ 0.07	ZnO	FeO 0.26
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Peacock


Neph Sy	31.57
Barium Carb	40.14
EPK	5.71
Flint	8.78
Red Iron Oxide	5.17
Ultrax (Zircopax)	8.62
Water	60



1-3 Second Dip



2-3 Second Dips




Reduction



Oxidation

SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.15		Alkaline Earths 0.85	
SiO ₂ 1.15	Collective "Al ₂ O ₃ " 0.20	Na ₂ O 0.12	K ₂ O 0.03	MgO 0.00	CaO 0.00
B ₂ O ₃	Al ₂ O ₃ 0.20	Li ₂ O	CuO	SrO	BaO 0.45
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.23
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO 0.16



Ceramic
Materials
Workshop

Peacock

Neph Sy	34.71
Barium Carb	44.14
EPK	6.28
Flint	9.66
Manganese Dioxide	2.84
Nickel Carb (Green)	2.37
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 4.82 :1		Alkali Metals 0.22		Alkaline Earths 0.78	
SiO ₂ 1.70	Collective "Al ₂ O ₃ " 0.35	Na ₂ O 0.17	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.29	Li ₂ O	CuO	SrO	BaO 0.67
TiO ₂ 0.00	NiO 0.06	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂ 0.10	CoO



Ceramic
Materials
Workshop

Peacock

Neph Sy	33.59
Barium Carb	42.72
EPK	6.08
Flint	9.35
Manganese Dioxide	2.75
Titanium Dioxide	5.50
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 3.38 :1		Alkali Metals 0.22		Alkaline Earths 0.78	
SiO ₂ 1.70	Collective "Al ₂ O ₃ " 0.50	Na ₂ O 0.17	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.29	Li ₂ O	CuO	SrO	BaO 0.67
TiO ₂ 0.21	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂ 0.10	CoO



Ceramic
Materials
Workshop

Peacock

Neph Sy	33.91
Barium Carb	43.12
EPK	6.14
Flint	9.43
Manganese Dioxide	2.78
Tin Oxide	4.63
Water	60



1-3 Second Dip



2-3 Second Dips


Oxidation



Reduction



SiO ₂ :Al ₂ O ₃ Ratio 5.80 :1		Alkali Metals 0.29		Alkaline Earths 0.71	
SiO ₂ 1.55	Collective "Al ₂ O ₃ " 0.27	Na ₂ O 0.16	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.27	Li ₂ O	CuO	SrO	BaO 0.61
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂ 0.09	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂ 0.09	CoO



Ceramic
Materials
Workshop

Peacock

Neph Sy	32.41
Barium Carb	41.21
EPK	5.87
Flint	9.02
Manganese Dioxide	2.65
Ultrax (Zircopax)	8.85
Water	60




1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 6.33 :1		Alkali Metals 0.22		Alkaline Earths 0.78	
SiO ₂ 1.85	Collective "Al ₂ O ₃ " 0.29	Na ₂ O 0.17	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.29	Li ₂ O	CuO	SrO	BaO 0.67
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂ 0.10	CoO



Peacock

Neph Sy	33.75
Barium Carb	42.92
EPK	6.11
Flint	9.39
Nickel Carb (Green)	2.30
Titanium Dioxide	5.53
Water	60



1-3 Second Dip




2-3 Second Dips



Oxidation

Reduction

SiO ₂ :Al ₂ O ₃ Ratio 3.02 :1		Alkali Metals 0.25		Alkaline Earths 0.75	
SiO ₂ 1.88	Collective "Al ₂ O ₃ " 0.62	Na ₂ O 0.19	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.32	Li ₂ O	CuO	SrO	BaO 0.74
TiO ₂ 0.23	NiO 0.07	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop

Peacock

Neph Sy	34.06
Barium Carb	43.32
EPK	6.17
Flint	9.48
Nickel Carb (Green)	2.33
Tin Oxide	4.65
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 4.82 :1		Alkali Metals 0.32		Alkaline Earths 0.68	
SiO ₂ 1.70	Collective "Al ₂ O ₃ " 0.35	Na ₂ O 0.17	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.29	Li ₂ O	CuO	SrO	BaO 0.67
TiO ₂ 0.00	NiO 0.06	Bi ₂ O ₃	SnO ₂ 0.09	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop

ceramicmaterialsworkshop.com

Peacock

Neph Sy	32.55
Barium Carb	41.39
EPK	5.89
Flint	9.06
Nickel Carb (Green)	2.22
Ultrox (Zircopax)	8.89
Water	60



1-3 Second Dip




2-3 Second Dips



Oxidation

Reduction

SiO ₂ :Al ₂ O ₃ Ratio 5.26 :1		Alkali Metals 0.25		Alkaline Earths 0.75	
SiO ₂ 2.05	Collective "Al ₂ O ₃ " 0.39	Na ₂ O 0.19	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.32	Li ₂ O	CuO	SrO	BaO 0.74
TiO ₂ 0.00	NiO 0.07	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop

Peacock

Neph Sy	32.99
Barium Carb	41.85
EPK	5.97
Flint	9.18
Titanium Dioxide	5.41
Tin Oxide	4.50
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 3.38 :1		Alkali Metals 0.32		Alkaline Earths 0.68	
SiO ₂ 1.70	Collective "Al ₂ O ₃ " 0.50	Na ₂ O 0.17	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.29	Li ₂ O	CuO	SrO	BaO 0.67
TiO ₂ 0.21	NiO	Bi ₂ O ₃	SnO ₂ 0.09	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop

Peacock

Neph Sy	31.55
Barium Carb	40.14
EPK	5.71
Flint	8.78
Titanium Dioxide	5.17
Ultrax (Zircopax)	8.62
Water	60



1-3 Second Dip




2-3 Second Dips

Oxidation



Reduction

SiO ₂ :Al ₂ O ₃ Ratio 3.69 :1		Alkali Metals 0.25		Alkaline Earths 0.75	
SiO ₂ 2.05	Collective "Al ₂ O ₃ " 0.56	Na ₂ O 0.19	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.32	Li ₂ O	CuO	SrO	BaO 0.74
TiO ₂ 0.23	NiO	Bi ₂ O ₃	SnO ₂	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop

ceramicmaterialsworkshop.com

Peacock

Neph Sy	31.84
Barium Carb	40.49
EPK	5.76
Flint	8.86
Tin Oxide	4.35
Ultrox (Zircopax)	8.70
Water	60



1-3 Second Dip



2-3 Second Dips

Oxidation




1-3 Second Dip



2-3 Second Dips

Reduction

SiO ₂ :Al ₂ O ₃ Ratio 6.33 :1		Alkali Metals 0.32		Alkaline Earths 0.68	
SiO ₂ 1.86	Collective "Al ₂ O ₃ " 0.29	Na ₂ O 0.17	K ₂ O 0.05	MgO 0.00	CaO 0.01
B ₂ O ₃	Al ₂ O ₃ 0.29	Li ₂ O	CuO	SrO	BaO 0.67
TiO ₂ 0.00	NiO	Bi ₂ O ₃	SnO ₂ 0.09	ZnO	FeO 0.00
Cr ₂ O ₃	ZrO ₂	P ₂ O ₅		MnO ₂	CoO



Ceramic
Materials
Workshop